

Freight service to Churchill will be delayed 24 to 48 hours. This is due to an on-track snow clearing machine coming off the rails while clearing snow north of Gillam. The machine become dislodged from the track when it encountered heavy drifting, however no damage to track and crews are working to place it back on the rails. Once this machine is moved, the train will proceed normally.

We apologize for the delay and we thank you for your dedication, your loyalty and understanding.